

# 加速传感器固定螺栓




## 直向固定螺栓




### 螺纹类型

- |                |              |
|----------------|--------------|
| 1 = 1/4"-28UNF | 6 = M5       |
| 2 = M6         | 7 = M4       |
| 3 = M8         | 8 = M10      |
| 4 = 快速拆卸       | 9 = 5/16"UNF |
| 5 = 10-32UNF   |              |



## 适配转换螺栓




### 螺纹类型

- |                |  |
|----------------|--|
| 1 = 1/4"-28UNF |  |
| 2 = M6         |  |
| 3 = M8         |  |
| 4 = 快速拆卸       |  |
| 5 = 10-32UNF   |  |
| 6 = M5         |  |
| 7 = M4         |  |
| 8 = M10        |  |
| 9 = 5/16"UNF   |  |

### 螺纹属性

- M = 阳  
F = 阴
- 六角形  
H = 是否需要



## 胶粘固定螺栓



### 螺纹类型

- |                |  |
|----------------|--|
| 1 = 1/4"-28UNF |  |
| 2 = M6         |  |
| 3 = M8         |  |
| 4 = 快速拆卸       |  |
| 5 = 10-32UNF   |  |
| 6 = M5         |  |
| 7 = M4         |  |
| 8 = M10        |  |
| 9 = 5/16"UNF   |  |

### 螺纹属性


- M = 阳  
F = 阴

### 直径


- |                     |
|---------------------|
| 1 = 25.4mm / 1.0"   |
| 2 = 19.05mm / 0.75" |
| 3 = 30.5mm / 1.2"   |
| 4 = 38.0mm / 1.5"   |

### 六角形

- H = 是否需要



## 磁座固定



### 螺纹类型


- |                |  |
|----------------|--|
| 1 = 1/4"-28UNF |  |
| 2 = M6         |  |
| 3 = M8         |  |
| 4 = 快速拆卸       |  |
| 5 = 10-32UNF   |  |
| 6 = M5         |  |
| 7 = M4         |  |
| 8 = M10        |  |
| 9 = 5/16"UNF   |  |

### 螺纹属性

- M = 阳  
F = 阴

### 直径

- |                     |
|---------------------|
| 1 = 25.4mm / 1.0"   |
| 2 = 19.05mm / 0.75" |
| 3 = 30.5mm / 1.2"   |
| 4 = 38.0mm / 1.5"   |



上海恒臻实业有限公司

Star Royal Industry & Engineering Co., Ltd.

电话Tele : +86 (21) 53076253 传真Fax : +86 (21) 53071679

Email: info@starroyal.com.cn  
www.starroyal.com.cn

DS.1119 iss.3